# iO Platform

Title: iO Platform 2.2.1.2264

Date: 27 May 2026

Product Family: iO Platform

Change Type: Bug Corrections

## 1. PURPOSE OF THE CHANGE

This Product Change Notice (PCN) summarizes the resolved issues introduced for software version 2.2.1.

## 2. PRODUCTS AFFECTED

iO mini
iO Gateway
iO Supervisor

## 2. POSSIBLE BREAKING CHANGE

### EV-4979 Modify OID Structure

A mismatch between the MID OID definition and the OID transmitted by the iO device has been corrected. The issue was caused by a missing ".1" at the end of the OID sent by the device.

This fix addresses mapping errors observed in certain trap receiver tools that did not properly recognize the trap structure due to the missing ".1" suffix.

This change does not impact the iO device's ability to send traps. However, it may affect how traps are interpreted by external systems. As a result, updates to trap receiver mappings may be required to include the ".1" suffix for proper alignment with the iO MIB.

**BEFORE THE FIX:**

| Trap | MIB OID | OID sent by iO device |
|---|---|---|
| ioNotificationActiveTrap | .1.3.6.1.4.1.5946.3.3.5.1.4.1 | .1.3.6.1.4.1.5946.3.3.5.1.4 |
| ioNotificationClearTrap | .1.3.6.1.4.1.5946.3.3.5.1.5.1 | .1.3.6.1.4.1.5946.3.3.5.1.5 |

**AFTER THE FIX:**

| Trap | MIB OID | OID sent by iO device |
|---|---|---|
| ioNotificationActiveTrap | .1.3.6.1.4.1.5946.3.3.5.1.4.1 | .1.3.6.1.4.1.5946.3.3.5.1.4.1 |
| ioNotificationClearTrap | .1.3.6.1.4.1.5946.3.3.5.1.5.1 | .1.3.6.1.4.1.5946.3.3.5.1.5.1 |

Multitel reserves the rights to change characteristics without notice. PCN_iO_Platform_27_05_2026 All rights reserved. Multitel 2026

## 3. BUG CORRECTIONS

**EV-4954** **Data Points - Negative Values Are Displayed As NaN**

**EV-4959** **Assets - Data Points- Statistics**
Incorrect maximum value when negative values are present.

**EV-4946** **Datasource - Asset Type To Display Should Be Set to All Assets By Default**
On the Asset page, the default selected option in the Asset Type To Display list is now set to “All Assets.”

**EV-4948** **Data Point - Not Able To Save Offset**
The Offset field value for Modbus data points of type Analog was not being saved correctly. This issue has now been fixed.

**EV-4951** **System Maintenance - Script Templates Clear Behavior**
Script templates are now separated between those installed by default on the i0 and those imported by users. Only user-imported templates can be deleted.

**EV-4902** **SNMP Table MIB Wrong Mapping for F1AIx and M1AIx**
Fixed an OID mapping issue between FxAIy data points and MxAIy data points.

**EV-4886** **Disabling IO Channel Hides Entire Interface**
On the i0 Channel page, disabling a channel caused all channels to disappear from the page. This issue has now been resolved.

**EV-4992** **Data Points**
Modbus register type and data type not editable.

Multitel reserves the rights to change characteristics without notice. PCN_i0_Platform_27_05_2026 All rights reserved. Multitel 2026

## 4. KNOWN ISSUES NOT YET FIXED

THEY WILL BE FIXED IN THE NEXT SOFTWARE VERSION

**EV-4957** **Notifications Configurations - Escalation Levels - Incorrect Status for Activation Traps**

When using escalation levels, during the sending of a trap upon notification deactivation, the status is incorrect. It reflects the next notification's status instead of the one being deactivated.

**EV-4906** **No Ethernet Port Warning** Display

When displaying the Connections page, an unnecessary warning message briefly appears. This message should only appear when both connections are disabled, which should not be possible..

**EV-4815** **Disabled User Still Has Access to the i0 device**

When a user is disabled while already logged in, they continue to have access to the i0 until they log out.

3710 Wilfrid Hamel Blvd.
Quebec, QC, G1P 2J2

Tel: 418.847.2255
Toll Free: 1.888.685.8483

info@multitel.com

Contact us today:
**multitel.com**

Multitel reserves the rights to change characteristics without notice. PCN_i0_Platform_08_04_2026 All rights reserved. Multitel 2026