Multitel

PRODUCT CHANGE NOTICE

FIRMSuite®

Multitel is pleased to announce the release of the new version 5.3.2 of FIRMSuite.

Get up to speed by upgrading your software to get the newest features providing better management and optimization of your space.

NEW FEATURES

MAJOR ENHANCEMENTS

Email and Notification

(BMM-708) - External email and a notification in the message center has been added to notify when value coming from a monitoring device are reported that the battery is failed.

Equipment Prioritization

(BMM-911) - A new equipment prioritization type field has been added in the right panel of the battery to enable the user to notify that maintenance on the powerplant is not required and that should not be considered to close the period cycle.

System Configuration

(BMM-1113) - A system configuration that can be only change by Multitel has been added to prevent wrong maintenance period assignation. As of now, the type of assignation will automatically set by the system configuration, so the user will not be able to change the type of assignation for a new period.

File Size

(BMM-1134) - FIRMSuite now accepts file size until 40mb.

MINOR ENHANCEMENTS

Warning External Email

(BMM-895) - The maintenance type and the quantity of warning triggered has been added to the warning external email.

BUG FIXES

Settings Module

(BMM-1137) - Fixed improper site suppression sync between FIRM Legacy and Skynet.

Asset Management Module

(BMM-924) - On the manual entry approval page, it is now possible to see the name of the equipment, a reference to the corresponding model and a possible access to see the specific information of this model.

(BMM-949) - Fixed improper tooltip visualization in the distribution module.

Battery Management Module

(BMM-1109) - Fixed improper unplanned maintenance completed confirmation message trigger.

(BMM-772) - Fixed improper value visualization in the historical readings interface.

(BMM-885) - Fixed improper save button behavior for maintenance locked.

(BMM-957) - Fixed improper unplanned maintenance validations.

(BMM-897) - The reserved by section in a maintenance will be open by default.

(Other) - Some spelling errors have been corrected through the application.

REQUEST YOUR UPDATE

AVAILABILITY

The new version 5.3.2 of FIRMSuite is available as of **August 2nd 2021.**

Multitel is committed to provide only the highest quality products for your needs. If you have questions regarding this product change notice, please contact your Multitel sales representative.

SPECIFICATION SHEET

2500 Jean-Perrin ST Suite 175
Quebec QC G2C 1X1
Tel: 418 847.2255
Toll Free: 1.888.685.8483
info@multitel.com

multitel-inc @Multitel_inc multitel.inc

Always know your at-risk sites and manage their weakest link today.

Contact us today:
multitel.com

Multitel reserves the rights to change characteristics without notice. PCN FIRMSuite 5.3.2
© All rights reserved. Multitel 2021.