

PRODUCT DISCONTINUED NOTICE PDN 2015-001

March 2015, release

Products

Various Accessories

Description

The present is to confirm the discontinuation of the following accessories used with Multitel's remote monitoring products.

Discontinued Part No.	Description	Replacement Part No.	Impact
M-4173	SDTA-02 3 PHASES 240VAC	M-3D-240-MD	Requires MODBUS interface and metal enclosure
M-4178	SDTA-02 3 PHASES 600VAC	M-3D-600-MD	Requires MODBUS interface and metal enclosure
LOSISC100	CURRENT TRANSDUCER - SPLIT CORE - 100A	M-4610-100-24	Requires 24Vdc supply and 10V analog input
LOSISC200	CURRENT TRANSDUCER - SPLIT CORE - 200A	M-4610-200-24	Requires 24Vdc supply and 10V analog input
LOSISC400	CURRENT TRANSDUCER - SPLIT CORE - 400A	Special order, please contact you Multitel representative for details.	
LOSISC600	CURRENT TRANSDUCER - SPLIT CORE - 600A 25 OHMS		
LOSISC600-E	CURRENT TRANSDUCER - SPLIT CORE - 600A 8 OHMS		
LOSISC1000-B	CURRENT TRANSDUCER - SPLIT CORE - 1000A		
M-4318	CTI-CURRENT TRANSDUCER INTERFACE 3-CHANNEL	No replacement required	
M-3551	ANEMOMETER KIT 150' CABLE	Special order, please contact you Multitel representative for details.	
M-3552	MOUNTING BRACKET ANEMOMETER		
M-3553	SENSOR WIND DIRECTION E/W 150' CABLE		



Dates

The discontinuity is effective as of **April 15th, 2015** and therefore, the above listed accessories will no longer be available after such a date. For some of the above accessories, replacement parts are **available immediately**. For more detailed information, please contact your Multitel point of contact for pricing and availability. Purchase order received with the old part number will be automatically switch to the new part number and an order acknowledgement will be sent to the customer to advise them of the change.

Requirements

There is no impact on the warranty neither the support of the product.

End of Product Change Notice

Contact us to find out more

By phone:

Multitel Customer Service
1-418-847-2255

Visit our WEB Site:

www.multitel.com