

# PRODUCT DISCONTINUATION NOTICE

This notice is to announce the discontinuation of MIRADOR Site Manager product series.  
Replacement part numbers are now available.



## DESCRIPTION

Discontinued Part No.	Description
M-3410-24-G	32 CHANNEL OUTPUT CARD, 24V
M-3410-48-G	32 CHANNEL OUTPUT CARD
M-3420-24-G	48 CHANNEL EVENT CARD, 24V DG
M-3420-48-G	48 CHANNEL BINARY CARD
M-3430-24-G	18 CHANNEL ANALOG CARD, 24V DG
M-3430-48-G	18 CHANNEL ANALOG CARD
M-3443	CPUIII, MIRADOR DISPLAY, REPLACE, DG
M-3445	DISPLAY MIRADOR 16 LEDS
M-3446	FRONT DISPLAY PCB CPU3
M-3611V	3X 50MV INPUT CHANNEL MODULE
M-3614V	3X 200V INPUT CHANNEL MODULE



M-3615V	5V/5V/5V INPUT VOLTAGE MODULE
M-3617V	200V/50MV/50MV INPUT CHANNEL MODULE
M-3619V	3X 60V INPUT CHANNEL MODULE
M-3620V	5V/50MV/50MV INPUT VOLTAGE MODULE
M-3621V	DAC/DAC/DAC VOLTAGE MODULE
M-3623V	100MV/100MV/100MV INPUT VOLTAGE MODULE
M-3631V	3X TEMPERATURE INPUT CHANNEL MODULE
M-3641V	3X 4-20MA INPUT CHANNEL MODULE
M-3651V	3X OSI INPUT CHANNEL MODULE
M-3661V	3X SDTA INPUT CHANNEL MODULE
M-3662V	3X 5VAC NON-ISOLATED FOR ACCI-01
M-3662V-MD	3X .5VAC NON-ISOLATED FOR CURRENT TRANSDUCER
M-3664V	AC/AC/AC VOLTAGE MODULE
M-3665V	AC/SDTA/SDTA VOLTAGE MODULE
M-3666V	2V/2V/2V VOLTAGE MODULE
M-3671V	200V/50MV/TEMPERATURE INPUT CHANNEL MODULE
M-3672V	5V/50MV/TEMPERATURE INPUT CHANNEL MODULE
M-3674V	200V/40V/TEMPERATURE VOLTAGE MODULE
M-3675V	3 INPUT CHANNEL +/-10V AC CURRENT VERTICAL MODULE
M-3676V	3 INPUT CHANNEL 200V/10V/200V VERTICAL MODULE
M-3677V	3 INPUT CHANNEL 200V/50MV/10V VERTICAL MODULE
M-3678V	3 INPUT CHANNEL 200V/10V/TEMPERATURE VERTICAL MODULE
M-3681V	HW/HW/TEMPERATURE VOLTAGE MODULE
M-3682V	ANEMOMETER/TEMPERATURE/DIRECTION
M-3684V	6 X 3V SINGLE CELL MODULE
M-3703V	600V/50MV/50MV INPUT VOLTAGE MODULE



M-3731V	200V/OSI/TEMPERATURE VOLTAGE MODULE
M-4320	CURRENT TRANSDUCER CALIBRATOR /1000/600/400AMP
M-5232	MIRADOR 18-CHANNEL SHUNTCARD 48V.
M-54/ANA-1	MIRADOR 18 CHANNEL SHUNTCARD
M-5800-00-48-01	CPUIII, MIRADOR SYSTEM ETH, -48V, DISPLAY LED
M-5800-00-48-02	CPUIII, MIRADOR SYSTEM ETH, -48V, DISPLAY LCD
M-5800-01-48-01	CPUIII, MIRADOR SYSTEM ETH, MODEM, -48V, DISPLAY LED
M-5800-01-48-02	CPUIII, MIRADOR SYSTEM ETH, MODEM, -48V, DISPLAY LCD
M-5805-00-24-02	CPUIII 24V DISPLAY LCD
M-5805-00-48-01	CPUIII, -48V, DISPLAY LED
M-5805-00-48-02	CPUIII, -48V, DISPLAY LCD
M-5805-01-48-01	CPUIII, MODEM, -48V, DISPLAY LED
M-5805-01-48-02	CPUIII, MODEM, -48V, DISPLAY LCD
M-5806-00-24-02	CPUI-CPUIII UPGRADE CARD, ETH, 24V, DISPLAY LCD
M-5806-00-48-02	CPUI-CPUIII UPGRADE CARD, ETH, -48V, DISPLAY LCD
M-5806-01-48-02	CPUI-CPUIII UPGRADE CARD, ETH, MODEM, -48V, DISPLAY LCD
M-5810-00-24	CPUI-CPUIII UPGRADE, ETH, 24V, DISPLAY LCD
M-5810-00-48	CPUI-CPUIII UPGRADE, ETH, -48V, DISPLAY LCD
M-5810-01-48	CPUI-CPUIII UPGRADE, ETH, MODEM, -48V, DISPLAY LCD
M-5815-00-24	CPUII-CPUIII UPGRADE, ETH, 24V, DISPLAY LCD
M-5815-00-48	CPUII-CPUIII UPGRADE, ETH, -48V, DISPLAY LCD
M-5815-01-48	CPUII-CPUIII UPGRADE, ETH, MODEM, -48V, DISPLAY LCD
M-5880-00	FUSION EXPANSION – SHELF CARD 1-5
M-5880-01	CPUIII, MIRADOR EXPANSION - SHELF, CARD 6-10
M-5880-02	CPUIII, MIRADOR EXPANSION - SHELF, CARD 11-15
M-5880-03	CPUIII, MIRADOR EXPANSION - SHELF, CARD 16-20



M-5880-04	CPUIII, MIRADOR EXPANSION - SHELF, CARD 21-25
M-5880-05	CPUIII, MIRADOR EXPANSION - SHELF, CARD 26-30
M-5880-O	FUSION 1U EXPANSION - 32 CH. OUTPUT CARD
M-8011	MIRADOR REFURBISH

### REPLACEMENT SOLUTION

The MIRADOR Site Manager product series can be easily substituted by the FUSION solution. FUSION supports natively MIRADOR I/O cards (Analog, Event, Output), allowing an efficient upgrade.

Multitel will continue to provide technical assistance and repair services for the MIRADOR Site Manager product series. If your organization does not have an active service contract with Multitel, a sales representative will be in touch with you in order to suggest a plan.

Our service contract provides a mean to protect your MIRADOR Site Manager investments, guarantee the technical assistance and the repair services for legacy Multitel products and reduce administrative efforts.

### EFFECTIVE DATE

Part numbers stated above are available for purchase until September 30<sup>th</sup>, 2018. After this date, purchase orders with MIRADOR part numbers won't be processed until a sales representative contacts you to review a possible replacement solution.



3710 Wilfrid Hamel Blvd.  
Quebec, QC, G1P 2J2  
Tel: 418.847.2255  
Toll Free: 1.888.685.8483  
info@multitel.com

Contact us today:  
[www.multitel.com](http://www.multitel.com)